

Aux2Car Interface Instruction Manual

Peripheral Electronics®, a division of AAMP of America™ 13160 56th Court Clearwater, Florida 33760 727-572-9255 or interface@peripheral-aamp.com ©2005 AAMP™ of Florida, Inc.

Table of Contents

CHAPTER 1	Pages
Installation Preparation (All Vehicles)	1-2
CHAPTER 2	
Dip-Switch Overview (REQUIRED)	3
Acura	4
Audi	5
Ford (Ford, Lincoln, Mercury)	6-7
GM (Buick, Cadillac, Chevy, GMC,	
Oldsmobile, Pontiac, Saturn)	8-10
Chrysler (Jeep, Dodge, Plymouth, Eagle)	11
Honda	12
Toyota	13
Volkswagen	14
CHAPTER 3	
Troubleshooting	15
Warranty/Warnings	16
FCC and Legal Information	17
Ford Appendix	18
GM Appendix 1	19
GM Appendix 2	20



Intro

Thank you for purchasing the Aux2Car interface. This interface will allow you to connect a line level audio input to you vehicle's factory radio without the use of a noisy RF modulator. The Aux2Car interface is the best way to add mobile video, satellite radio, MP3 players or other hand held media devices to your factory radio.

Installation Preparation

This chapter provides information required for the installation of the Aux2Car adaptor, it must be read by all users.

Thank you for purchasing the Aux2Carl adaptor. Since the Aux2Car will work in many different vehicles the following steps must be taken to ensure that it is set up correctly for the vehicle it is being installed in.

Before Installation

To prevent damage to your vehicle and the interface, take the following precautions.

NOTE: If the vehicle is equipped with an on-board drive or navigation computer, do not disconnect the battery cable. If the battery cable is disconnected, the computer memory may be lost. Under these conditions, use extra caution to avoid causing a short circuit during installation. If your radio has a security code make sure you know the code and how to enter it prior to removing the battery cable. The radio will require this code to operate when the battery terminal is reconnected.

1. Do not install the unit in the following locations:

A. Locations exposed to direct sunlight


B. Locations where hot air flows from the car's heater

First Step (For All Vehicles)

The first and most important step in using the Aux2Carl is setting the dip-switches on the interface; this makes the Auxillary source compatible with the vehicle it is being installed in. The Aux2Carl adaptor will not work if this step is not followed correctly.

IMPORTANT!!! Dip Switch settings must be made while unit is unplugged from vehicle. Changes to dip switch settings will not be recognized untill unit is powered down, then powered up again.

The dip switches can be found on the side of the interface which connects to the source. Switches are in the "ON" position when they are switched down. Aux2Carl settings for each vehicle can be found on the vehicles installation page. Refer to the index to find the page number within this manual that covers your vehicle.



Connect Auxiliary source to female RCA input



Vehicle Installation

In this chapter you will learn how to install the Aux2Carl adaptor in specific vehicles.

The Aux2Carl adaptor connects to your car radio using a vehicle specific cable harness. Browse to the specific section for your vehicle to learn what cable you need and how to set up the Aux2Carl and install in your vehicle. Below is an overview of all Aux2Carl settings.

Dip-Switch Overview

The dip switches can be found on the side of the Aux2Car. Switches are in the "ON" position when they are switched DOWN. Aux2Carl settings for each vehicle can be found on the vehicles installation page. Refer to the index to find the page number that covers your vehicle.

Programming Dip Switch settings Quick Reference

	1	2	3	4	5	6	7	8
Acura	on	off	off	on	off	off	off	on
Audi/VW	on	off	off	off	off	off	off	on
Ford	off	on	off	off	off	off	off	on
Ford Focus	on	on	off	off	off	off	off	on
GM E&C	off	off	on	off	off	off	off	on
GM Class 2	on	off	on	off	off	off	off	on
GM XM	off	on	on	off	off	off	off	on
Chrysler new	off	off	off	on	off	off	off	on
Chrysler old/Honda	on	off	off	on	off	off	off	on
Toyota	on	on	off	on	off	off	off	on

Please consult vehicle specific section for important installation instructions

Acura

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR ALL ACURAS

1	2	3	4	5	6	7	8
on	off	off	on	off	off	off	on

- All Models (1992-2002) Connector behind the radio, use the PX HCH2 cable and the Aux2Carl settings above.
- TL 1999 to 2002 use Honda cable behind the radio
- Acura NSX, SLX, and MDX (1996 and Up) Not Compatible.
- Acura's with navigation are not compatible.

OPERATION

Switch to the Aux2Carl adaptor by pressing the CD button on the radio. This step may take up to three minutes for the radio to initialize. Some radio models require pressing "Seek >" once to start playing the auxillary source.

Audi

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

Before connecting any cables to the Aux2Carl you must set the dip switchs to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

	1	2	3	4	5	6	7	8
ĺ	on	off	off	off	off	off	off	on

- All Models (1998-2004) Pre-wired 13-pin cable in the left-rear trunk of all Audi vehicles use the PXHAD1
- Audi A8 (2003-2004) Not Compatible.
- Audi A6 (2004) Not Compatible.

OPERATION

Once you connect the Aux2Carl adaptor, turn on your radio. A CD icon will appear on the display of your radio showing that the Aux2Carl adaptor is ready to use.

Switch to the Aux2Carl adaptor by pressing the CD/ Mode button on the radio.

Ford (Ford, Lincoln, Mercury)

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

if you use PXHFD1, PXHFD2 make sure that you connect the Black wire to ground and the Yellow wire to constant 12V+. *If you don't know the location of constant 12V+, please use a Volt meter, or consult a Ford dealership.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR FORD FOCUS & COUGAR

1	2	3	4	5	6	7	8
on	on	off	off	off	off	off	on

SETTINGS FOR ALL OTHERS

1	2	3	4	5	6	7	8
off	on	off	off	off	off	off	on

See the next page for a full list of vehicles as well as plug location in each.

OPERATION

Switch to the Aux2Carl adaptor by pressing the "CD" button on the radio.

If you would like to connect Aux2Carl adaptor to 2004 - Town Car, Grand Marquis, Marauder, LS and Ford Crown Victoria, please see Ford appendix, page 19.

Model	Year(s)	IPOD Location and Notes
Ford		
		PXHFD2 connector behind Radio.
Crown Victoria	1995-1997	Premium Audio System
0		PXHFD1 (Rear Control Unit) in the trunk.
Crown Victoria	1995-1997	JBL / Luxury System
Crown Victoria	1998-2003	PXHFD3 connector behind Radio.
Escape	2001-2004	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Econoline	1997	Premium Audio System
Econoline	1998-2004	PXHFD3connector behind Radio.
Escort	1997-2004	PXHFD2 connector behind Radio.
Excursion	2000-2004	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Expedition	1997-1998	Premium Audio System
Expedition	1999-2004	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Explorer	1995-1997	Premium Audio System
		PXHFD1 (Rear Control Unit) in the trunk.
Explorer	1995-1997	JBL / Luxury System
Explorer	1998-2004	PXHFD3 connector behind Radio.
F-150		PXHFD2 connector behind Radio.
Pick-Up	1997	Premium Audio System
F-Series Pick-Up	1998-2004	PXHFD3 connector behind Radio.
		PXHFD4 connector behind Radio.
Focus	2000-2003	6 Disc IPOD only
HN80 Heavy		PXHFD2 connector behind Radio.
Truck	1996-1997	Premium Audio System
Mustang	2001-2004	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Ranger	1995-1997	Premium Audio System
Ranger	1998-2004	PXHFD3connector behind Radio.
Sport Trac	2000-2004	PXHFD3 connector behind Radio.
Taurus	1996-2005	PXHFD1 (Rear Control Unit) in the trunk.
Thunderbird	2000-2004	PXHFD3 connector behind Radio.
Windstar	1999-2004	PXHFD3 connector behind Radio.

Model	Year(s)	IPOD Location and notes
	1641(5)	IF OD Location and notes
Lincoln		
Aviator	2002-2004	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Continental	1995-1997	Premium Audio System
		PXHFD1 (Rear Control Unit) in the trunk
Continental	1995-1997	JBL / Luxury System
Continental	1998-2004	PXHFD3 connector behind Radio.
LS	2000-2003	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Mark VIII	1995-1998	Premium Audio System
		PXHFD2 connector behind Radio.
Navigator	1997-1998	Premium Audio System
Navigator	1999-2004	PXHFD3 connector behind Radio.
		PXHFD2 connector behind Radio.
Town Car	1995-1997	Premium Audio System
		PXHFD1 (Rear Control Unit) in the trunk.
Town Car	1995-1997	JBL / Luxury System
Town Car	1998-2003	PXHFD3 connector behind Radio.
Mercury		
		PXHFD4 connector behind Radio.
Cougar	1999-2004	6 Disc IPOD only
		PXHFD2 connector behind Radio.
Grand Marquis	1995-1997	Premium Audio System
		PXHFD1 (Rear Control Unit) in the trunk.
Grand Marquis	1995-1997	JBL / Luxury System
Grand Marquis	1998-2003	PXHFD3 connector behind Radio.
Mountaineer	1997	PXHFD1 (Rear Control Unit) in rear passenger side panel.
		PXHFD2 connector behind Radio.
Mountaineer	1997	Premium Audio System
Mountaineer	1998-2004	PXHFD3 connector behind Radio.
Sable	1996-2005	PXHFD1 (Rear Control Unit) in trunk/rear.
Tracer	1997-2004	PXHFD2 connector behind Radio.
		PXHFD2 connector behind Radio.
Villager	1997-1998	Premium Audio System
Villager	1999-2002	PXHFD3 connector behind Radio.
		•

GM (Buick, Cadillac, Chevy, GMC, Pontiac, Saturn)

PLEASE READ

*1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible with the Aux2CarlADAPTER.

*2000-2004 Radios with built in CD player ARE compatible.

Separate OEM CD (1995-2000) must be disconnected to use the Aux2Carl adaptor.

2003 – 2005: If XM mode is used, the you must not have GM factory original XM tuner installed. If installed you must unplug it for Aux2Carl adaptor to work.

Corvette: Please see GM-Corvette appendix, page # 20

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

GM's use one of three cables (PXHGM1, PXHGM2, PXHGM3); use the cable that fits, and follow GM table connection guide

If you use "GM-C" cable, please connect the loose Yellow wire to constant 12V+

GM has 3 protocols, please determine by GM table in this guide, your car's protocol, and set the Aux2Carl accordingly.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR CLASS 2

OPERATION FOR CLASS 2 Switch to the Aux2carl adaptor by pressing the "Aux" or "Source" button.

1	2	3	4	5	6	7	8
on	off	on	off	off	off	off	on

SETTINGS FOR XM

OPERATION FOR XM Switch to the Aux2car adaptor by pressing the "Band" button, until you see XM1.

The screen will change to D1 T1 (Disc 1, Track 1)

1	2	3	4	5	6	7	8
off	on	on	off	off	off	off	on

2003 – 2005: If XM mode is used, the you must not have GM factory original XM ttuner installed. If installed you must unplug it for Aux2Can adaptor to work.

SETTINGS FOR E & C

OPERATION FOR E&C Switch to the Aux2Carladaptor by pressing the "Aux" or "Source" button.

1	2	3	4	5	6	7	8
off	on	on	off	off	off	off	on

Model	Year(s)	IPOD Location and Notes
Buick		Notes for Buick:Requires GM factory CD data cable part # 12344003 if not pre-wired in trunk.
Century	1997-2003	PXHGM2 Cable in trunk.Protocol: E&C
Le Sabre	2000- 2002	PXHGM2 Cable in trunk.Protocol: Class 2
Le Sabre	1995-1999	PXHGM2 Cable in trunk.Protocol: E&C
Park Ave	1995-2005	PXHGM2 Cable in trunk.Protocol: E&C
Rainer	2004	PXHGM3 cable behind RadioProtocol: XM / Class 2
Regal	1995-2003	PXHGM2 Cable in trunk.Protocol: E&C
Riviera	1996-1999	PXHGM2 Cable in trunk.Protocol: E&C
Rendezvous	2003-2005	PXHGM3 cable behind RadioProtocol: XM / Class 2
Roadmaster	1995-1996	PXHGM2 Cable in trunk.Protocol: E&C
Skylark	1996-1998	PXHGM2 Cable in trunk.Protocol: E&C
Cadillac		
Catera	2000-2001	PXHGM2 Cable in trunk.Protocol: Class 2
Catera	1997-1999	PXHGM2 Cable in trunk.Protocol: E&C
DeVille	1995-1999	PXHGM2 Cable in trunk.Protocol: E&C
DeVille	2000-2001	PXHGM2 Cable Behind Glove Comp. Protocol: E&C
DeVille	2001-2005	PXHGM2 Cable Behind Glove Comp. Protocol: Class 2
Eldorado	1995-2002	PXHGM2 Cable in trunk.Protocol: E&C
Escalade	1999-2002	PXHGM1 Cable behind HeadunitProtocol: E&C
Escalade	2003-2005	PXHGM3 Cable behind HeadunitPro- tocol: Class 2
Seville	1995-2001	Location: Center Console – PXHGM2 cable; Protocol E&C
Seville	2002-2004	Location: Center Console – PXHGM2 cable; Protocol Class 2
Chevrolet		
Astro Van	1996-2005	PXHGM1 Cable behind HeadunitProtocol: E&C
Avalanche	2003-2005	PXHGM3 Cable behind HeadunitProtocol: Class 2
Avalanche	2002	PXHGM1Cable behind HeadunitProtocol: E&C
Blazer	1998-2002	PXHGM1 Cable behind HeadunitProtocol: E&C
Camaro	1997-2002	PXHGM1Cable behind HeadunitProtocol: E&C
		AM/FM/Cassette with "TAPE/AUX" button.
Cavalier	2003-2005	PXHGM3 Cable behind HeadunitProtocol: XM
Cavalier	1996-1999	PXHGM1 Cable behind HeadunitProtocol: E&C
Corvette	1997-2004	PXHGM2 Cable in trunk.Protocol: E&Clf cable not in trunk, please see Corvette Notes.

Chevrolet - continue		
Equinox	2005	PXHGM3 Cable behind HeadunitPro- tocol: XM / Class 2
Impala	2000-2005	PXHGM3 Cable behind HeadunitPro- tocol: Class 2
Impala	1995-1999	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Lumina	1996-1999	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Malibu	1997-2000	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Monte Carlo	2000-2005	PXHGM3 Cable behind HeadunitPro- tocol: Class 2
Monte Carlo	1996-1999	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Silverado	2003-2005	PXHGM3 Cable behind HeadunitPro- tocol: Class 2
Silverado	1996-2002	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Suburban	2003-2005	PXHGM3 Cable behind HeadunitPro- tocol: Class 2
Suburban	1995-2002	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Tahoe	2003-2005	PXHGM3 Cable behind HeadunitPro- tocol: Class 2
Tahoe	1995-2002	PXHGM1 Cable behind HeadunitPro- tocol: E&C
Trailblazer	2004	PXHGM3 Cable behind HeadunitPro- tocol: XM / Class 2
Venture	2004-2005	PXHGM3 Cable behind HeadunitPro- tocol: XM / Class 2
Venture	1997-1999	PXHGM1 Cable behind HeadunitPro- tocol: E&C

	Υ	1	ir .		·
GMC	ļ		Model	Year(s)	IPOD Location and Notes
Jimmy	1998-2002	PXHGM1 Cable behind Headunit- Protocol: E&C	Oldsmobile	1	Requires GM factory data cable Part #
Envoy	2004	PXHGM3 Cable behind Headunit- Protocol: XM / Class 2			12344003 if not pre- wired in trunk.
Envoy	1999-2001	PXHGM1 Cable behind Headunit- Protocol: E&C	Achieva	1996-1998	PXHGM3 Cable in trunk.Protocol: E&C
Savana	1999-2000	PXHGM1 Cable behind Headunit- Protocol: E&C	Alero	1999-2000	PXHGM2 Cable in trunk.Protocol: E&C
Sonoma	1998-2002	PXHGM1 Cable behind Headunit- Protocol: E&C	Alero	2003-2004	PXHGM3 Cable behind HeadunitPro- tocol: XM
Safari	1996-2005	PXHGM1 Cable behind Headunit- Protocol: E&C	Aurora	1995-1999	PXHGM2 Cable in trunk.Protocol: E&C
Sierra	1995-2002	PXHGM1 Cable behind Headunit- Protocol: E&C	Aurora	2001-2004	PXHGM2 Cable in trunk.Protocol:
Sierra	2003-2005	PXHGM3 Cable behind Headunit- Protocol: Class 2	Bravada	1997-2001	Class 2
Suburban	1995-2002	PXHGM1 Cable behind Headunit- Protocol: E&C	Diavaua	1991-2001	behind HeadunitPro- tocol: E&C
Yukon; Yukon- Denali;Yukon- XL	1995-2002	PXHGM1 Cable behind Headunit- Protocol: E&C	Bravada	2004	PXHGM3Cable be- hind HeadunitProto- col: XM / Class 2
Yukon; Yukon- Denali;Yukon-	2003-2005	PXHGM3 Cable behind Headunit- Protocol: Class 2	Cutlass	1997-1999	PXHGM2 Cable in trunk.Protocol: E&C
Pontiac			Cutlass Supreme	1995-1997	PXHGM2Cable in trunk.Protocol: E&C
Aztek	2003-2005	PXHGM3 Cable behind Headunit- Protocol: XM / Class 2	Eighty-Eight	1996-1999	PXHGM2Cable in trunk.Protocol: E&C
Bonneville	1996-1999	PXHGM1 Cable behind Headunit- Protocol: E&C	Intrigue	1998-2001	PXHGM2Cable in trunk.Protocol: E&C
Bonneville	2000-2005	PXHGM2 Cable in trunk.Protocol: Class 2	LSS	1996-1999	PXHGM2Cable in trunk.Protocol: E&C
Firebird	1996-2002	PXHGM1 Cable behind Headunit- Protocol: E&C	Regency	1997-1998	PXHGM2Cable in trunk.Protocol: E&C
Grand Am	2003-2005	PXHGM3 Cable behind Headunit- Protocol: XM /Class 2	Silhouette	2004	PXHGM3 Cable behind HeadunitPro- tocol: XM
Grand Am	1996-2000	PXHGM1 Cable behind Headunit- Protocol: E&C	Silhouette	1996-1999	PXHGM1 Cable be- hind HeadunitProto-
Montana	2004-2005	PXHGM3 Cable behind Headunit- Protocol: XM / Class 2			col: E&CRadio must be AM/FM/CASS.
Montana	1999-2000	PXHGM1 Cable behind Headunit- Protocol: E&C			
Sunfire	1996-1999	PXHGM1 Cable behind Headunit- Protocol: E&C			
Sunfire	2003-2005	PXHGM3 Cable behind Headunit- Protocol: XM			
TransSport	1996-1998	PXHGM1 Cable behind Headunit- Protocol: E&C			
Vibe	2004-2005	PXHGM3 Cable behind Headunit- Protocol: XM / Class 2			
Saturn]		
All Models	1995-1999	PXHGM2 Cable in trunk.Protocol: E&C			
		If not prewired, you must use two Saturn cables:			
		GM Part# 21023550 & 21023253			

Chrysler (Chrysler, Jeep, Dodge, Plymouth, Eagle)

Make sure the Aux2Carl adaptor is compatible with your vehicle, Check for "Disc ^" printed on preset button "1". If you see it, it means that your radio can control the Aux2Carl adaptor.

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

Remove the radio to see which cable fits your vehicle, and then refer to settings below. **Do not force cables in.**

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR "CHRYSLER OLD DIN" CABLE

	1	2	3	4	5	6	7	8
ı	on	off	off	on	off	off	off	on

Use the PXHCH1 cable with vehicles 1995-1999/2000.
-Connects behind the radio

SETTINGS FOR "CHRYSLER NEW DIN" AND "10 PIN CABLES

1	2	3	4	5	6	7	8
off	off	off	on	off	off	off	on

Use the PXHCH2 cable with vehicles 1999-2001.
Use the PXHCH3cable with vehicles 2002-2004.
-Connects behind the radio

OPERATION FOR

Switch to the Aux2Carl adaptor by pressing the "CD" or "MODE" button.

Honda – All Honda except Passport

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR HONDA

1		2	3	4	5	6	7	8
of	f	off	off	on	off	off	off	on

Compatible with Honda 1992- 2004 except:

Honda Passport

2003-2004 Accord ; 2003-2004 Element ; 2004 +

Honda S2000

Honda uses 2 cables:

1992- 1997 – PXHCH2 cable 1998-2004 – PXHHD1 cable

Connects behind the radio

OPERATION

Switch to the Aux2car adaptor by pressing the "CD" button.

Toyota / Scion / Isuzu / Honda-Passport

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR TOYOTA

	1	2	3	4	5	6	7	8
ı	on	on	off	on	off	off	off	on

Toyota 1998 – 2005 – Connects behind the radio with PXHTY1

2003 and newer :4Runner; Sequoia; Rav4; Prius; Sienna; Tundra; Tacoma; Highlander Must use Toyota cable adapter, part # 08695-00370

Isuzu 1998-2003 – Connects behind the radio with PXHTY1

Scion 2003-2005 – Connects behind the radio (Must use Toyota cable adapter, part #08695-00370)

Toyota Matrix uses the PXHGM3 cable with GM class 2 settings. Please see GM section.

Cars that need cable part #08695-00370, can only be purchased from Toyota dealerships.

Call your nearest Toyota dealership, and ask for the parts dept.

OPERATION

Switch to the Aux2Carl adaptor by pressing the "CD" button.

Volkswagen

Make sure you have your radio's theft protection code before you attempt installation. When you reconnect power to the battery, you will need to enter this code. Information about the theft protection code can be found in your vehicle's audio operation manual.

Before connecting any cables to the Aux2Carl you must set the dip switches to the correct position. If you set the dip-switches after you have connected cables to the interface, you must disconnect and reconnect them for the Aux2Carl to operate.

DIP SWITCHES MUST BE SET BEFORE YOU PLUG IN THE Aux2Carl!!!

SETTINGS FOR ALL VW'S

1	2	3	4	5	6	7	8
on	off	off	off	off	off	off	on

There are two different cables for Volkswagen vehicles. The PXHVW1 cable is for pre-wired vehicles with the CD Changer connection in the trunk. The PXHVW2 is for direct connection behind the radio

If you use the PXHVW2 cable make sure you connect the black and white cable to ground

If Aux2Carl is not being recognized, sound is noisy and/or Keys on radio not properly working please Disconnect the Aux2car adapter from trunk, and plug to radio using VW front cable directly to radio

Cause: VW prewired cable to trunk not shielded and is causing noise from Aux2Carl datalines, into audio lines

OPERATION

Switch to the Aux2Carl adaptor by pressing the "CD" button on the radio.



Symptom	Cause	Remedy
No Power	Blown fuse	Replace fuse with same amp. Rating. If the fuse blows again, call tech support.
No Power	Bad connection	Check cable connection.
Alternator noise is heard (Changes with gas)	Wrong wiring creates ground loop.	Call tech support or ask a local car audio shop.
Radio can't recognize Aux2car adaptor	Bad cables or cables are not connected properly between converter box and car radio	Check connection and cables, push in firmly.
Aux2car adaptor suddenly is not recognized any more	Bad connection or loss of power to interface	Unplug the black converter box from Radio and plug again
Radio can't recognize Aux2car adaptor	Wrong selection on dip switch in the converter box	Select the right protocol for you car. (See Page 3)

For technical support call 800-477-2267 9:30 am-6pm EST. MON - FRI

Warranty and Warning

One Year Limited Warranty

The quality controls used in the manufacture of this product will ensure your satisfaction. This warranty applies only to the original purchaser of this product from an authorized dealer

This warranty covers any supplied or manufactured parts of this product that, upon inspection by Peripheral Electronics authorized personnel, is found to have failed in normal use due to defects in material or workmanship. This warranty does not apply to installation expenses.

Attempting to service or modify this unit, operating this unit under conditions other than those recommended or voltages other than the voltage indicated on this unit, will render this WARRANTY VOID.

Unless otherwise prescribed by law, Peripheral Electronics shall not be liable for any personal injury, property damage and or any incidental or consequential damages of any kind (including water damage) resulting from malfunctions, defects, misuse, improper installation or alteration of this product.

All parts of this Peripheral Electronics product are guaranteed for a period of 1 year as follows:

Within the first 12 months from date of purchase, subject to the conditions above, Peripheral Electronics will repair or replace the product at their discretion, if it is defective in material or workmanship providing it is returned to an Authorized Peripheral Electronics Dealer, with PROOF OF PURCHASE from an authorized dealer.

Warning:

This equipment may be reset by unintentional electrostatic discharge during operation. Exposure to direct sunlight or extreme heat may cause damage or malfunction.

Caution

- 1. Use of headphones while operating an automobile or moving vehicle is not recommended and is unlawful in some countries and areas.
- 2. Be careful and attentive on the road. Stop operation of the Aux2Carl adaptor if you find it disruptive or distracting while driving. The driver of a motor vehicle should not operate the Aux2Carl ADAPTER while driving.

FCC Class B Radio Frequency Interference Statement

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encourages to try to correct the interference by one or more of the following measures:

- 1. Reorient or relocate the receiving antenna.
- 2. Increase the separation between the equipment and receiver.
- 3. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- 4. Consult the dealer or an experienced radio/television technician for help.

Notice 1: The changes or modifications not expressly approved by the party responsible for compliance could void the user authority to operate the equipment.

Notice 2: Shielded interface cables, if any, must be used in order to comply with the emission limits.

Copyrights, warnings, and other information.

The illustrations, technical information, data and descriptions contained in this publication are subject to change without notice.

This publication, together with all information contained in it, and all intellectual property rights on this publication remain the property of Peripheral Electronics. The user may not pass this publication on to third parties.

No liability will be accepted for any inaccuracies or omissions in this publication, although due care has been taken to make it as complete and accurate as possible

FORD Appendix

Aux2Carl Adaptor Connection 2004 - Town Car, Grand Marquis, Marauder, LS and Ford Crown Vic.

1. Preparing the Ford-12pin Cable

Take the PXHFD4 cable and cut off the black 12-pin plug. You will use only the cable and big White 22 pin connector (connects to the iPod2car).

2. Connection to the Vehicle

There are two connectors located behind the radio, a 16 pin connector and a 24 pin connector.

We will first work with the 16 pin connector.

16pin Connector:

Red to 16pin connectors Orange/Black cable (Pin #9)

Blue to 16pin connectors Gray cable (Pin #10)

Green to 16pin connectors Light Green/Red cable (Pin #1)

Pink to 16pin connectors Violet cable (Pin #2)

Yellow to 16pin connectors Light Blue/Pink cable (Pin #7)

White to 16pin connectors Tan cable (Pin #8)

Brown to 16pin connectors Light Green/Black cable (Pin #6)

24pin Connector:

Gray to 24pin connectors Violet/Light Blue cable (Pin #1)

Orange to 24pin connectors Black/Light Green cable (Pin #24)

*Important Note:

Some vehicle production runs do not have a cable plugged into the 16pin pin connector on the back of the headunit. If you are installing in this type of vehicle you can use another cable (For example the Honda cable) and shave the plastic off of the white 22pin connector and remove the pins inside. These pins can then be inserted into the holes on the back of the vehicles stereo. Call technical support if you need further assistance with this option.

3. Technical Support

If you have any questions or need any support, please feel free to call 800-477-2267 from 9:30am-6pm EST.

GM Appendix 1 Corvette Aux2car Adaptor Connection to Chevrolet Corvette

Most Corvettes are pre-wired to the trunk. In case you can't find the connector in the trunk, please do the following:

1. Preparing the GM-A Cable

Take the PXHGM1 cable and cut off the Black and Red plug. You will then have two cables in your hands. One cable with the big white 22 pin connector and 1 with a small white 9 pin connector. You will use only the cable with the big White 22 pin connector (connects to the Aux2Car).

2. Connection to the Vehicle

There are two connectors located behind the radio, one is black and the other is grey. We will first work with the grey connector.

Grey Connector:

Blue to Connector Brown+White (Pin 11, the 1st pin)
Red to Connector Green+White (Pin 12, the 2nd pin)
Black to Connector Black+White (Pin 13, the 3rd pin)
Yellow to Connector Dark Green (Pin 15, pin 14 is empty)*

Black Connector:

Orange to Black Connector thick **Orange** (Pin 10, the last pin, +12v) Brown to Black Connector **Black+White** (Pin 5, the middle, Ground)

3. Technical Support

If you have any questions or need any support, please feel free to call 800-477-2267 from 9:30am-6pm EST.

NOTE: CORVETTE 2005 IS NOT COMPATIBLE

GM Appendix 2 Cadillac; Oldsmobile; Buick that use E&C protocol (1995 – 1999) - Cable in trunk can't be found

Most 1995 – 1999 Cadillac's, Oldsmobile's & Buick's are pre-wired to the trunk. In case you can't find the connector in the trunk, please do the following:

1. Preparing the PXHGM1 Cable

Take the PXHGM1 cable and cut off the Black and Red plug, you will then have two cables in your hands. One cable with the big white 22 pin connector and 1 with a small white 9 pin connector. You will use only the cable with the big White 22 pin connector (connects to the Aux2Car).

2. Connection to the 32 pin connector behind the Radio

Yellow to 32 pin connector, Pin # 1 DK Green cable (Data)

- * Black to 32 pin connector. Pin # E9 Black + White cable (Audio GND)
- * Blue to 32 pin connector, Pin # E10 Brown + White cable (Left Audio)
- * Red to 32 pin connector, Pin # E11 DK Green +White cable (Right Audio)
 Orange to 32 pin connector, Pin # F1 Orange cable (12V+)

Brown to 32 pin connector. Pin # E16 Black + White cable (Ground)

3. Technical Support

If you have any questions or need any support, please feel free to call 800-477-2267 from 9:30am-6pm EST.

^{*}Some cars don't have the Brown /White cable to Pin # E10, the Dark Green/White cable to pin #E11 and the Black /White cable to pin #E9.

In such case, please use from any other cable (i.e. Ford cable) from the 22pin White connector, the female pin. Just remove from the white 22 connector a Female pin and use it to connect to GM radio missing pin. It fits perfectly. To remove pin from 22 pin connector, you can shave of the plastic with a knife until you reach the pin.

Please check out our other products including:

iPod2car

Interface that connects an iPod to most factory radios

NeoChanger

Complete universal CD changer that connects to most factory stereos



Peripheral Electronics®, a division of AAMP of America™ 13160 56th Court Clearwater, Florida 33760 727-572-9255 or interface@peripheral-aamp.com ©2005 AAMP™ of Florida, Inc. Free Manuals Download Website

http://myh66.com

http://usermanuals.us

http://www.somanuals.com

http://www.4manuals.cc

http://www.manual-lib.com

http://www.404manual.com

http://www.luxmanual.com

http://aubethermostatmanual.com

Golf course search by state

http://golfingnear.com

Email search by domain

http://emailbydomain.com

Auto manuals search

http://auto.somanuals.com

TV manuals search

http://tv.somanuals.com