



### Features:

- Point and Shoot Simplicity
- Status LCD
- 2MB Internal Memory
- Web Cam functionality
- USB Download
- Photo editing software

### System Requirements:

- \*Windows® OS (98SE/2000/ME/NTXP):
- Pentium II 300, Celeron, AMD Athlon processor or higher
- 32MB RAM
- 125MB available hard disk space
- CD-ROM drive
- Available USB port
- 24-bit color display adapter or above

### Kit Includes:

- User Guide
- USB Cable
- 3 AAA Batteries
- Wrist Strap
- CD-Rom

### Resolution:

VGA

### Pixel Resolution:

640 x 480

### Shutter Speed:

1/8uS-1/30sec

### Aperture Range:

F 2.8

### Exposure Control:

Auto

### Display:

Status LCD

### Focus Range:

1.5M - infinity

### White Balance:

Auto

### Frame Rate in web camera Mode:

7 fps QVGA

### Imaging Sensor Type:

CMOS

### Memory:

2MB SDRAM Internal

### Compression:

JPEG

### PC / Mac Interface:

USB 1.1

### Power:

3 AAA Batteries

### Bundled Software:

ArcSoft PhotoImpression

## Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>