


ChannelPlus Video Hubs








To control your video devices, add a modulator with IR repeating, an IR target and an IR emitter. Point a remote control at the target in the bedroom and IR pulses are repeated by the emitter, controlling the DVD player in the den. Any or all of the television ports may have targets connected.

Expanding the modulator inputs


Add a model H881 active combiner and a single modulator input becomes eight.

OpenHousetm modules attach from the top



Expanding the television outputs

You may connect as many as 8 more H838s to the outputs of a master H838 for a total of 64 television outlets. The longest recommended coax run should not exceed 150'. (That is a total of the coax from master to slave and from slave to TV.)



Specifications: typical @ 25°C ± 5°	G	
Gain:	H838HHR	H838BID
CATV/Ant input to TV output	3dB	3dB
Modulator input to TV output	-10dB	-10dB
TV output to CATV/Ant input	na	-15dB
(5-42MHZ reverse channel)		
Isolation		
Modulator input to CATV/Ant	>80dB	>35dB
Bandwidth		
Forward	5-806MHz	54-806MHz
Reverse	na	5-42MHz
Max CATV/Antenna input (64 channels)	20dBmV	20dBmV
Power supply (370-086 included)	15 VDC @ 300mA	15 VDC @ 300mA

Things To Watch For:

Herringbone interference on modulator channel (diagonal lines): You may have chosen a channel number that is not completely vacant. Distant UHF stations may not be watchable, but will cause interference if you try to create a new channel at the same frequency. Also, cable companies often have extra signals where there should be none. Try moving the modulator channel to another number. You may have to add a low pass filter to remove the cable company noise. If the filter does not work, try adding a DC-block to remove common mode interference. Herringbone interference on many channels, including modulator channels (disappears when you remove the CATV/antenna feed): The RF amplifier can be overloaded by abnormally strong signals. Often, you can cure the problem with a simple attenuator. Use a variable attenuator and try to find a signal level where the interference just disappears. Sometimes, the problem is one station is far stronger than the rest. In this case, attenuating all of the signals with a simple attenuator may cause the desired stations to be weak (snowy). You must reduce the strength of the only offending station. A common FM trap will help if the problem is a nearby FM tower. If the problem is a nearby TV station, often the station management can provide suitable filters.

FCC Requirements:

THIS PRODUCT COMPLIES WITH FCC REQUIREMENTS. A SYSTEM USING THIS DEVICE WILL COMPLY WITH FCC REQUIREMENTS. USE ONLY VIDEO MODULATORS THAT COMPLY WITH PART 15 OF THE FCC RULES AND HAVE 25dBmV MAX OUTPUT LEVELS. FAILURE TO DO SO MAY VOID THE USER'S AUTHORITY TO OPERATE THIS EQUIPMENT. THE H838HHR IS SUITABLE FOR USE WITH AN ANTENNA OR WITH CATV SYSTEMS.

New ChannelPlus products are added all the time.


Download from Www.Somanuals.com. All Manuals Search And Download.

IR Accessories Control video devices from any room.





or a satellite receiver. These modulators


AV modulators




AV modulators (for service center) Create a new TV channel for a front door camera. Some models feature Cat-5 input connections.











Coax panels

Distribute antenna or cable TV to every room of the house. Some models include bi-directional amplifiers for interactive cable systems. Some models include modulator inputs and IR engines.



Wall plates Wall plate systems for all rooms. The typical room gets TV and telephone. The Home office wall plate adds data ports. The media center wall plate adds satellite feeds.








Termination blocks for the CAT-5 cables,

Ethernet hubs, Bring the Internet to any




Data hubs



every room. Starter hub adds RJ-31X jack for security system dialer.

RF splitters and telephone punch downs. When it is time to upgrade, just snap this module out and replace with one of more of the more sophisticated units.


Starter systems



Service center

enclosures A full line of OpenHouse compatible enclosures, from simple, inexpensive mounting plates to high capacity in-wall cabinets. AC outlets can be mounted inside the cabinets using a UL listed accessory

Accessories & Wall Plates







- eone office -- Media center -

- moon leoiqT

Home office -

- eoifto emoH

- netres center -

Best

Better

Good

VT , anond - moon lsoigyT

- netia center - moor lesidyT

Best

Better

.. booð

data or 1 to 4 telephone lines. RG-6 coax handles television (antenna or entertainment: Cat-5, 4-UTP (4 Unshielded Twisted Pairs) wire handles wiring.) Two types of wire are used for communication and The cables in an OpenHouse run from the various rooms of the house

We recommend the following pre-wire schemes . Run these wires from

Cable), satellite dish, cable modem, or AV modulator signals. (An AV

modulator creates new TV channels for front door camera, DVD player, a

phone, TV, ethernet, satellite receiver, cable modem, hi-speed data

phone, TV, ethernet, satellite receiver, AV modulators, hi-speed data

3 BG-6

2 KG-9

2 BG-6

3 Cat-5

2 Cat-5

1 Cat-5

Home Office

phone, TV, ethernet, satellite receiver

phone, satellite receiver, AV modulators

3 Cat-5

2 Cat-5

1 Cat-5

Media Center

phone, TV, ethernet, satellite receiver, AV modulators

3 KG-6

3 KG-6

3 KG-6

phone, TV, ethernet, cable modem

phone, TV, ethernet

2 BG-6

1 KG-9

1 BG-6

2-JeO 2

2 Cat-5

1 Cat-5

VCR or a satellite receiver.)

Typical Room

the service center to the rooms indicated.

phone, TV, cable modem

directly to the service center location.(This is known as 'home run' WITING a house for OpenHouse





3001 Enterprise Street, Brea, CA 92821-6213, U.S.A. 714-996-4100 * 800-999-5225 * FAX 714-996-4900 * www.channelplus.com

Warranty

Multiplex Technology, Inc. warrants this product to be free from defects in materials and workmanship for a period of one year from the date of purchase or MTI will repair, or at its option, replace the defective product. To obtain warranty service, call MTI for a return material authorization (RMA) number and return the product prepaid to Multiplex Technology, Inc., 3001 Enterprise Street, Brea, CA 92821, Attention: Customer Service. Please put the RMA number on the outside of the carton.

Any implied warranty arising from the sale of the product including implied warranties of merchantability and fitness for purpose are limited to the warranty stated above. MTI shall not be responsible for losses or damages or expenses, whether direct, consequential or incidental arising from the use of or the inability to use this product. Some states do not allow limitations on how long the implied warranty lasts or the exclusion or limitation or incidental or consequential damages, so the above limitations and exclusions may not apply to you. This warranty gives you specific legal rights, and you may have other rights which may vary from state to state.



Free Manuals Download Website <u>http://myh66.com</u> <u>http://usermanuals.us</u> <u>http://www.somanuals.com</u> <u>http://www.4manuals.cc</u> <u>http://www.4manuals.cc</u> <u>http://www.4manuals.cc</u> <u>http://www.4manuals.com</u> <u>http://www.404manual.com</u> <u>http://www.luxmanual.com</u> <u>http://aubethermostatmanual.com</u> Golf course search by state

http://golfingnear.com Email search by domain

http://emailbydomain.com Auto manuals search

http://auto.somanuals.com TV manuals search

http://tv.somanuals.com