

# MODEL T10117 BIG-MOUTH DUST HOOD w/STAND INSTRUCTIONS

#### Introduction

The Model T10117 Big-Mouth Dust Hood provides a method of effective dust collection for machines that do not come equipped with dust ports, or for additional dust collection when needed. The dust hood adjusts vertically from 29" to 49".




Figure 1. Model T10117 identification.

### **Inventory**

After removing the contents of the shipping package, lay them out and refer to the **Parts Breakdown** on the back page to inventory the components.

If you need help with your new dust hood, call our Tech Support at: (570) 546-9663.

#### **Assembly**

Refer to **Figure 1** and the **Parts Breakdown** illustration to aid you in the following assembly procedure.


#### To assemble your dust hood:

- **1.** Thread the four foot pads into the base.
- 2. Secure the vertical support assembly onto the base by threading the 3/8"-16 x 1" hex bolt, lock washer, and flat washer through the bottom of the base and into the support assembly.
- 3. Install the angle pivot bracket onto the top of the vertical support assembly with the two  $\frac{1}{4}$ "-20 x  $\frac{1}{2}$ " hex bolts.
- **4.** Use the  $\frac{3}{8}$ "-16 x  $\frac{1}{2}$ " knob to install the dust tube onto the angle pivot bracket.
- 5. Slide the hood mounting tube onto the dust tube and secure it in place with one of the 1/4"-20 x 3/8" knobs.
- 6. Insert the dust hood into the mounting tube, then secure it in place with the remaining 1/4"-20 x 3/8" knob and wing nut.

## **Operation**

Adjust the angle pivot and vertical support assembly so that the hood is positioned close enough to the operation to be effective without interfering with it. Then, securely clamp a 4" dust hose between the hood assembly and your dust collection system.

# **T10117 Parts Breakdown**



REF	PART#	DESCRIPTION	QTY
1	PT10117001	DUST TUBE	1
2	PT10117002	DUST HOOD	1
3	PT21521003	KNOB 1/4-20 X 3/8	2
4	PT10117004	ANGLE PIVOT BRACKET	1
5	PB19	HEX BOLT 1/4-20 X 1/2	2
6	PT10117006	KNOB 3/8-16 X 1-1/2	1
7	PT10117007	BOTTOM VERTICAL SUPPORT	1
8	PT21521008	KNOB 5/16-18 X 3/4	1

REF PART #		DESCRIPTION	QTY
9	PT21521009	TOP VERTICAL SUPPORT	1
10	PLW04	LOCK WASHER 3/8	1
11	PT10117011	BASE	1
12	PT10117012	FOOT PAD M6-1 X 20	4
13	PW02	FLAT WASHER 3/8	1
14	PCAP14	CAP SCREW 3/8-16 X 1	1
15	PT21521015	HOOD MOUNTING TUBE	1
16	PWN02	WING NUT 1/4-20	1

COPYRIGHT © NOVEMBER, 2008 BY GRIZZLY INDUSTRIAL, INC., REVISED SEPTEMBER, 2009 (TS) WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.

#TS11344 PRINTED IN TAIWAN

Free Manuals Download Website

http://myh66.com

http://usermanuals.us

http://www.somanuals.com

http://www.4manuals.cc

http://www.manual-lib.com

http://www.404manual.com

http://www.luxmanual.com

http://aubethermostatmanual.com

Golf course search by state

http://golfingnear.com

Email search by domain

http://emailbydomain.com

Auto manuals search

http://auto.somanuals.com

TV manuals search

http://tv.somanuals.com