

Front Panel Controls and LCD

Continuous or pulsed ultrasonics

Time, energy, and temperature control modes.
Program a Pulse Temp and a Max Temp to enable True Temperature Control

Fully programmable pulsing, in time or energy (joules)

Experiment progress indicator

Process monitoring

Navigation Keys
Press the Up key or Enter key to initiate a change to the current settings, then use the Up, Down, Left, and Right keys to adjust values.

Press the Left and Right keys to select control modes, to move horizontally between digits, and to move between different result screens.

Press the Enter key to accept control setting changes.

Preset Key
Press the Preset key to select a memory location to save the current sample-processing program, or to recall stored settings.

ESC Key
Press the ESC key to return to the ready screen when modifying control settings.

Pause Key
Press the Pause key to pause an ultrasonic cycle. Press the Pause key again to resume current cycle.

Start/Stop Key
Press the Start/Stop key to turn ultrasonics on/off.

Reset Key
Press the Reset key to reset errors and alarms.

Test Key
Press and hold the Test key to turn on sonics.

Microtip Key
Press the Microtip key when using a microtip probe. This limits amplitude to 70%, thus preventing damage to the probe.

Confirm Settings

Start-up Test

Micro Tip

Reset Alarm

CAUTION
- PRESS μ BEFORE USING MICROTIP
- MAXIMUM 70% AMPLITUDE ON MICROTIP

Sonifier®

Operational Sequence

The Sonifier features varied parameter settings to precisely control the ultrasonic treatment of your sample.

The delivery of ultrasonic energy may be precisely controlled by selecting the mode that best suits your application.

For more information, refer to your Sonifer manual.

Setting a Timed Experiment

1. Turn on power and wait for the LCD to show rdy (ready) and current mode icons on the top two rows.
2. Press the Up key once to get into operating mode selection. Current selected operating mode icon will blink.
3. Use the Left and Right keys to select Continuous mode, then press the Enter key to confirm the selection. Navigation will continue to the control mode selection.
4. Use the Left and Right keys to select Time mode, then press the Enter key to confirm the selection. Navigation will continue to the parameters area.

5. Time parameter numbers will flash. Use the Up, Down, Left, and Right keys to enter the desired value, then press the Enter key to confirm the selected value.

NOTICE: When setting parameters, pressing the ESC key will take you back to the rdy screen. Any parameter changes that were not confirmed using the Enter key will be lost.

Save/Load Sample Processing Programs (Presets)

Save Preset

1. Press the Preset key while on the ready screen. The Preset icon, 'LO', and two digits which indicate the Preset memory locations will appear on the LCD.
2. Press the Left and Right keys to change the parameter from Load to Save. The Preset icon, 'SA', and two digits which indicate the Preset memory locations will appear on the LCD.
3. The digits under the Preset icon show the preset number. Select the Preset number where you wish to save the current parameters using the Up and

Down keys, then press the Enter key. This will save the current settings to the selected memory location and will return to the ready screen.

NOTICE: Press the ESC key to exit without saving the preset.

Load Preset

1. Press the Preset key while on the ready screen. The Preset icon, 'LO', and two digits which indicate the Preset memory locations will appear on the LCD.
2. Select the Preset number from where you wish to load the parameters using the Up and Down keys, then press the Enter key. This will load the saved preset parameters and will return to the ready screen.

NOTICE: Press the ESC key to exit without loading a preset.



BRANSON

Americas

Branson Ultrasonics Corp.
41 Eagle Road
Danbury, CT 06813-1961
T: 800-732-9262
F: 203- 796-2250
www.bransonultrasonics.com

Europe

Branson Ultraschall
Niederlassung der Emerson
Technologies GmbH & Co. OHG
Waldstrasse 53-55
63128 Dietzenbach, Germany
T: +49-6074-497-0
F: +49-6074-497-199
www.branson.eu

Asia

Branson Ultrasonics (Shanghai) Co., Ltd.
758 Rong Le Dong Road
Song Jiang, Shanghai, PRC, 201613
T: 86-21-3781-0588
F: 86-21-5774-5100
www.branson-china.com

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>