
DRM-1804X Installing on Windows95

Microsoft's Windows 95 does not have direct support for Pioneer's DRM-1804X. To access the DRM1804X in the Windows 95 operating system, follow the instructions below:

- 1.) Add device driver to the CONFIG.SYS file:
 <ASPI Manager>
 C:\PIONEER\DRD18ASP.SYS /D:MSCD000

Note: <ASPI Manager> is dependent on the user's SCSI controller.
Reference your SCSI controller manufacturer.

Example: Adaptec 1542CF SCSI controller:
 C:\ADAPTEC\ASP4DOS.SYS
 C:\PIONEER\DRD18ASP.SYS /D:MSCD000

Note: Future Domain SCSI controller will not need an ASPI manager

Example: Future Domain SCSI controller
 C:\PIONEER\DRD18FD.SYS /D:MSCD000

- 2.) Add latest MSCDEX to AUTOEXEC.BAT file:

Example:
 C:\WINDOWS\COMMAND\MSCDEX.EXE /D:MSCD000

- 3.) Add "DRD18ASP.SYS" to the IOS.INI file.
 - a.) goto Windows directory
 - b.) copy IOS.INI file to IOS.ORG
 - c.) Edit IOS.INI file
 - d.) locate the section named "[CDunsafe]" near the bottom of the file.
 - e.) add "DRD18ASP.SYS" name under the "[CDunsafe]" section
 i.e. [SafeList]
 ...
 predir.exe ; Printer redirect

 [CDunsafe]
 drd18asp.sys ; Pioneer 1804x
 - f.) exit IOS.INI and reboot the computer system

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>