
Corrections on the Owner's Manual

Specifications of "GUITAR IN jack" on page 95 in the Owner's Manual contain errors.

INCORRECT:

Minimum input level : +3 dBV (1.4 V) , (INPUT volume at 7)

Maximum input level : -25 dBV (0.05 V) , (INPUT volume at 10)

CORRECT:

Maximum input level : +3 dBV (1.4 V) , (INPUT volume at 7)

Minimum input level : -25 dBV (0.05 V) , (INPUT volume at 10)

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>