

QX7 APPLICATION GUIDELINE 1.2***Unlocking VI/II Input Rev. 3*****Introduction**

This feature allows you to correct a glitch when the QX7 drive is not responding to VI/II input signal. This should be used on drives prior to Rev. 4. (See software revision document).

Programming

Keystroke	LED Display
Press Setup/program/monitor key	Setup
Press Setup/program/monitor key	Program Search
Down arrow 11 times	Program Input Terminals
Read/Write	F Terminal Forward (NO)
Up arrow 6 times	S3 Terminal Set Speed 3 (NO)
Read/Write	S3 Terminal *Flashing* Set Speed 3 (NO)
Down arrow 14 times	S3 Terminal *Flashing* Unassigned (NO)
Read/Write	S3 Terminal Unassigned (NO)
Setup/Program/Monitor 3 times	Output Frequency 0.0Hz

Notes

Re-check to assure all parameters are set properly.

Free Manuals Download Website

<http://myh66.com>

<http://usermanuals.us>

<http://www.somanuals.com>

<http://www.4manuals.cc>

<http://www.manual-lib.com>

<http://www.404manual.com>

<http://www.luxmanual.com>

<http://aubethermostatmanual.com>

Golf course search by state

<http://golfingnear.com>

Email search by domain

<http://emailbydomain.com>

Auto manuals search

<http://auto.somanuals.com>

TV manuals search

<http://tv.somanuals.com>