# Important Information — Dell OptiPlex 790/990

### **About Warnings**

MARNING: A WARNING indicates a potential for property damage, personal injury, or death.

## **System Board**

The Dell OptiPlex 790/ 790 computers are now shipped with a new system board without the following components:

- 1. Heatsink
- 2. Power supply thermal sensor (Desktop chassis only)

### **Heatsink Removal**

The following image displays an earlier version of the system board shipped with the heatsink.




Figure 1. System Board of an earlier version of the system board with the heatsink

All system boards shipped with the following BIOS versions or higher will NOT contain the heatsink.

Computer Model	BIOS version
OptiPlex 790/990	A11

If the BIOS is downgraded to an earlier version than the version listed above, an error message will be displayed.



Regulatory Model: D09M, D05D, D03S, D01U Regulatory Type: D05D001, D03S001, D01U001 2012 - 04

## **Power Supply Thermal Sensor Removal**

The power supply thermal sensor is removed from the desktop chassis only.



Figure 2. System Board with the thermal sensor and heatsink removed

- 1. thermal sensor connector-1 and cable removed
- 2. chipset heatsink removed
- 3. thermal sensor connector-2



**NOTE:** If you have replaced your system board with a new system board for the Desktop chassis, always ensure that the BIOS version is A11 or higher.



WARNING: If you do not update the BIOS, you may receive Alert! Chipset heat sink not detected error message during the power-on self test (POST).



**NOTE:** With the new system board, it is tested and found that all component temperatures are within the specifications.



**NOTE:** With the new system board, there is no impact on the system performance.

#### Information in this publication is subject to change without notice.

#### © 2012 Dell Inc. All rights reserved.

Reproduction of these materials in any manner whatsoever without the written permission of Dell Inc. is strictly forbidden.

Trademarks used in this text:  $Dell^TM$ , the DELL logo, Dell Precision $^TM$ , Precision  $ON^TM$ , Express  $Charge^{TM}$ , Latitude $^TM$ , Contrino $^TM$ , OptiPlex $^TM$ , Vostro $^TM$ , and Wi-Fi Catcher $^TM$  are trademarks of Dell Inc. Intel $^TM$ , Pentium $^TM$ , Xeon $^TM$ , Centrino $^TM$ , Centrino $^TM$ , and Celeron $^TM$  are registered trademarks of Intel Corporation in the U.S. and other countries. AMD $^TM$  is a registered trademark and AMD Opteron $^TM$ , AMD Phenom $^TM$ , AMD Sempron $^TM$ , AMD Athlon $^TM$ , ATI Radeon $^TM$ , and ATI FirePro $^TM$  are trademarks of Advanced Micro

Devices, Inc. Microsoft®, Windows®, MS-DOS®, Windows Vista®, the Windows Vista start button, and Office Outlook® are either trademarks or registered trademarks of Microsoft Corporation in the United States and/or other countries. Blu-ray Disc™ is a trademark owned by the Blu-ray Disc Association (BDA) and licensed for use on discs and players. The Bluetooth® word mark is a registered trademark and owned by the Bluetooth® SIG, Inc. and any use of such mark by Dell Inc. is under license. Wi-Fi® is a registered trademark of Wireless Ethernet Compatibility Alliance, Inc.

Other trademarks and trade names may be used in this publication to refer to either the entities claiming the marks and names or their products, Dell Inc. disclaims any proprietary interest in trademarks and trade names other than its own.

Free Manuals Download Website

http://myh66.com

http://usermanuals.us

http://www.somanuals.com

http://www.4manuals.cc

http://www.manual-lib.com

http://www.404manual.com

http://www.luxmanual.com

http://aubethermostatmanual.com

Golf course search by state

http://golfingnear.com

Email search by domain

http://emailbydomain.com

Auto manuals search

http://auto.somanuals.com

TV manuals search

http://tv.somanuals.com